

Report ID: 26,195,060 Version: 2 24 Aug 2024 Created:

Make:	Mitsubishi	Model:	Colt Plus	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	<b>Registration:</b>	DEU898	Reg Expiry:	23 Jul 2025	Engine	1	<u> </u>	1
WoF Expiry:		Odometer:	119,156 Kms	Good No:	26195060	Oil level	~		
VIN:	JMYLTZ27W5Z000204	Next Service:	129000	Service Histor	<b>y:</b> No	Smoke & fumes	~		<u> </u>
						Performance	~		<u> </u>
	port is not a warranty	avation is made	for one and miles as	Dauta hava nat	heen discontinued on	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0			SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc 6/6			TIN	S SC	Operation	~		
R = rust PT = paint defe				$\int$	JHIH	Noise	~		
C = crack				+		Clutch			~
P = pin dent						CV joints	~		-
* = decals	sc 916			-NL	S D SC	Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs SC SC SC W SC						Performance	~		
		Note: son	ne defects & blemishes	may not be disr		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread			
						Left front 3.5 mm			
						Right front		.5	mm
						Left rear			mm
						Right rear		2.5	
Conditions During Body Inspection: Dry							2.0		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
2wd	<b>j</b>					Suspension performance	~		
2.00						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation			<u> </u>
Interior Comments						Operation 🖌			
	Average					Head lights			
Seats						-	~		
Carpets	Average					Tail lights	<b>v</b>		
	Average					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
General (	Comments					Window winder FR	~		
	<u></u>					Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		1
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>
Engine Tir	ming Mechanism:	Timina				Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Lvidence	or carri bert neplac			11113.		Reversing camera			~
Inspected	d by: Uriah Pepene					Date: 22 Jul 202	4		

I have read and understood this condition guide.

Name: .....

Signature: .....