

Basic Vehicle Condition Guide

Report ID: 26,197,177

Pass

Version:

Fnaine


Created: 09 Aug 2024

Fail

Make: Model: Ford Territory **Body Style:** SUV Year: 2014 Registration: HSK563 Reg Expiry: 14 Dec 2024 WoF Expiry: **Odometer:** 05 Jan 2025 171,253 Kms **Good No:** 26197177 VIN: 6FPAAAJGATEP69083 Next Service: 179459 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor stone chips on windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil residue on and under engine/Transmission (possible leak) Bump stoppers wearing

All wheel drive

Inte	rior	Comments

Seats	Drivers seat torn, Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Inspected by:

Partial service history (recorded up to 105567kms) Passenger window and rear drivers side window not operating Minor damage to key (unable to use a key ring)

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Jaykib Collins

Evidence of Cam Belt Replacement: No Kms:

~		
~		
~		
~		
		•
'		
'		
~		
~		
/		
		~
~		
/		
		_
'		
~		
l depth	of tyre	es)
5	.5	mm
6	0.0	mm
3.5		mm
4.0		mm
	Yes	
/		
~		
~		
~		
~		
~		
>		
V		
> > >		
	V	
	V	
V	~	
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	V	
V	V	
V V V	V	
V V V V	V	
VVVVI	V	
\(\times \) \(\t	V	
VVVVI	<i>V</i>	
\(\times \) \(\t	V	
	ン	マ

I have read and understood this condition guide.

Name:

Signature:

23 Jul 2024

Date: