

Basic Vehicle Condition Guide

Report ID: 26,197,183


Version: 1

Created: 24 Jul 2024

Make: Model: Foton Tunland **Body Style:** Utility Year: 2018 Registration: LJQ937 Reg Expiry: 29 May 2024 WoF Expiry: **Odometer:** 102,206 Kms **Good No:** 26197183 VIN: LVAV2MBB9JC001404 Next Service: 111000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Nudge bar front bumper, drivers door needs replacing bad rust,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Minor transmission and oil leak,minor underbody surface rust on parts of chassis and diff doors have visable rust

<u>Interior Comments</u>			
Seats	wear,minor stains .		
Carpets	wear,minor stains ,		
Panels	Good		
Dashboard	Good		

General Comments

Drives okay,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara Date: 23 Jul 2024

Name:

	Pass	Fail	N/A
Engine	1 033	1 dii	IN//
Oil level	V		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	I		ļ.
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	V		
Hand Brake	V		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		.6	mm
Right front	6.6		mm
Left rear	9.1		mm
Right rear			mm
Spare	Yes		
Suspension			
Suspension performance	V		
Steering performance	·		
Shock absorbers	\ <u>\</u>		
Air Conditioning / Heater			
Operation	\ <u>\</u>		
Electrical / Accessories			
Head lights	·		
Tail lights	<i>V</i>		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	<i>y</i>		
Window winder FL	1		
Window winder FR	\(\times \)		
Window winder RL	<i>v</i>		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	·		
CD (basic test only)	V		
Number of keys	1		<u> </u>
Central locking			
Remote locking	<i>V</i>		
Sat. Nav. (basic test only)		-	.,
Reversing camera			-
neversing camera	-		

Signature: