

Basic Vehicle Condition Guide

Report ID: 26,203,077

Version: 1


Created: 25 Jul 2024

Pass Fail N/A

Make: Model: Holden Vectra **Body Style:** Sedan Year: 2003 Registration: **BPB398** Reg Expiry: 04 Aug 2024 WoF Expiry: **Odometer:** 02 Aug 2024 166,281 Kms **Good No:** 26203077 VIN: W0L0ZCF6931126748 Next Service: Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front bumper crack

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak

Interior Comments		
Seats	Good	
Carpets	driver side floor mat torn	
Panels	Good	
Dashboard	Good	

General Comments

Inspected by:

Remote key button's worn Code required to unlock radio Noise from steering rack

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Kilipati Mae

Evidence of Cam Belt Replacement: No Kms:

-				
~				
~				
~				
~				
~				
~				
~				
~				
~				
		~		
~				
~				
Wheel bearings Brakes				
·				
•				
l dontk	of tyre) 		
	-	mm		
		mm		
		mm		
		mm		
	Yes			
1	1			
~				
~				
~				
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
~				
~				
~				
~				
~				
~				
~				
~				
~				
~				
	 			
	~			
	V			
1	<i>V</i>			
1	\(\times \)			
1	\(\times \)			
1	\(\times \)	<i>V</i>		
		マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ		

I have read and understood this condition guide.

Name:

Signature:

25 Jul 2024