

Basic Vehicle Condition Guide

Report ID: 26,203,374


Version: 2

Created: 09 Aug 2024

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2013 Registration: HCU537 Reg Expiry: 20 Jul 2024 WoF Expiry: **Odometer:** 13 Jul 2025 233,469 Kms **Good No:** 26203374 VIN: MMAJRKA40DD00364 Next Service: 243,500 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Good | | |
| Panels | Average | | |
| Dashboard | Good | | |

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Samuel Weir

Evidence of Cam Belt Replacement: Yes

Kms: 136,355

| | Da | Ea:I | NI/A | |
|--|------------------|---------|----------|--|
| Engino | Pass | Fail | N/A | |
| Engine Oil lovel | | | | |
| Oil level | | | | |
| Smoke & fumes | \(\times \) | | | |
| Performance | | | | |
| Noise | • | | | |
| Cooling System | | | | |
| Coolant condition Performance | | | | |
| | / | | | |
| Radiator / Hoses (visual) | | | | |
| | | | | |
| Operation | | | | |
| Noise Clutch | | | | |
| | | | <i>V</i> | |
| CV joints Wheel bearings | | | | |
| Wheel bearings Brakes | | | | |
| Performance | ., | | | |
| Hand Brake | • | | | |
| | l donth | of turn |) | |
| Tyres (lowest observed tread depth of tyres) Left front 10.0 mm | | | | |
| Right front | 10.0 | | - | |
| Left rear | 10.5 | | mm | |
| Right rear | 4.5 | | | |
| | 4 | | mm | |
| Spare Yes Suspension | | | | |
| Suspension performance | V | | | |
| Steering performance | <i>V</i> | | | |
| Shock absorbers | - | ~ | | |
| Air Conditioning / Heater | | _ | | |
| Operation | v | | | |
| Operation Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | · · | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | \(\times \) | | | |
| Wipers (front & rear) | | | | |
| Window winder FL | ン ン ン ン | | | |
| Window winder FR | · | | | |
| Window winder RL | · / | | | |
| Window winder RR | V | | | |
| Rear view mirrors | V | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | V | | | |
| Number of keys | 2 | | 1 | |
| Central locking | · | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | - | | V | |
| | | | <u> </u> | |
| Reversing camera | | | V | |

I have read and understood this condition guide.

Name:

Signature:

05 Aug 2024

Date: