

Report ID: 26,205,310 3 Version: 12 Dec 2024 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Sedan		Pass	Fail	N/A
Year:	2013	Registration:		Reg Expiry:		Engine	1		1
WoF Expiry:		Odometer:	94,110 Kms	Good No:	26205310	Oil level	~		
VIN:	7AT0C139X24102579	Next Service:	104,109	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	boon dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		$-\infty$				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				710		Operation	~		
PT = paint def	ect NP				17111	Noise	~		
C = crack						Clutch			~
P = pin dent	HP				2414	CV joints	~		
* = decals	- dle	10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
,, significan		S				Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	8.0 mm		mm
						Right front	8.	.0	mm
						Left rear	8.	.0	mm
Conditions During Body Inspection: Wet						Right rear	8.0 mm		mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD						Suspension performance	<		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Cood					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	and Caral					Wipers (front & rear)	~		
	Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Enging Ti	ming Mechanism	Timina	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	ог сант вен керіас	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Allan Young Date: 09 Aug 2024									

I have read and understood this condition guide.

Name:

Signature: