


<b>Make:</b> Nissan	<b>Model:</b> Fuga	<b>Body Style:</b> Sedan
<b>Year:</b> 2004	<b>Registration:</b> LUH226	<b>Reg Expiry:</b> 20 May 2024
<b>WoF Expiry:</b> 29 Sep 2024	<b>Odometer:</b> 157,170 Kms	<b>Good No:</b> 26209478
<b>VIN:</b> 7AT0DH8GX17200872	<b>Next Service:</b> no service history	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**  
S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



**Body Inspection Comments** Note: some defects & blemishes may not be displayed in the diagram

Spoiler on boot poorly attached. Front grill chrome trim loose. Front bumper poor fit. Roof lining pinned up. Drivers seat worn

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**  
. Brakes appear to be new , All engine covers loose. Tyres have been stretched too rims. Engine has oil leaks

**Interior Comments**

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

**General Comments**  
Radio sound system does not work. A/c, heater and cameras work at time of inspection. Knocking from front suspension. possible wheel bearings Vehicle needs wheel alignment. Drivers window had difficulty going down. No Jack.Highstop vehicle has two. Front passenger seat broken

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Reuben Harvey Date: 30 Jul 2024

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints			✓
Wheel bearings		✓	
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	6.0	mm	
Right front	6.0	mm	
Left rear	6.0	mm	
Right rear	6.0	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers		✓	
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights		✓	
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR		✓	
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)		✓	
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera	✓		

I have read and understood this condition guide. Name: ..... Signature: .....