


Report ID: 26,210,655

Version: 2



Evidence of Cam Belt Replacement:

Inspected by: Lukin Koveskali

No Reversing camera Date: 31 Jul 2024 I have read and understood this condition guide. Signature:

						Create	d: 3	1 Jul 20	24
Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/
Year:	2016	Registration:	JWB773	Reg Expiry:	07 Dec 2024	Engine			
WoF Expiry:	25 Jul 2025	Odometer:	85,615 Kms	Good No:	26210655	Oil level	~		
VIN:	MMU148PK0GH64206	Next Service:	100519	Service Histor	r y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mile	age. Parts have no	t been dismantled or	Noise	~		
diagnostic te	sting undertaken. The	vehicle has beer	n driven up to 50k	m/h from cold. The	Vendor recommends	Cooling System			
a full mechar	nical inspection prior to	purchase and ti	nis can be arrange	ed for an additional	cnarge.	Coolant condition	~		
	S					Performance	~		
Key:	3	$=$ $\langle 0 \rangle$		$\leq (0)$		Radiator / Hoses (visual)	~		
S = scratch D = dent	NE				A	Transmission			
R = rust						Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	110				ZUUL	CV joints	~		
* = decals	- Alk				BID SP	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv – signincan	S SC		SS			Performance	~		
Rody Inc	oection Comments	Note: son	ne defects & blemi	shes may not be dis	played in the diagram	Hand Brake	~		
body IIIs	occion comments					Tyres (lowest observed tread	d depth	of tyre	;s)
						Left front	8	.0	mm
						Right front	8	.0	mm
						Left rear	5	.0	mm
Conditions During Body Inspection: Wet						Right rear	5	.0	mm
Tect						Spare		Yes	
<u>Under Ca</u>	irriage & Under Bor	nnet Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories	l		
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ard Good					Window winder FL	~		
	<u> </u>					Window winder FR	~		
General Comments						Window winder RL	~		
Reverse camera not working						Window winder RR	~		
пеатей ѕеа	ts not working					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1	<u> </u>	
Road Conditions During Test Drive: Wet						Central locking	~		
			****			Remote locking	~		
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			V
			_			·			