

Report ID: 26,212,929 5 Version: 12 Dec 2024 Created:

Make:	Volkswagen	Model:	Polo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2012	<b>Registration:</b>	GEJ566	<b>Reg Expiry:</b>	15 Jan 2025	Engine			
WoF Expiry:	23 Feb 2025	Odometer:	103,530 Kms	Good No:	26212929	Oil level	~		
VIN:	WVWZZZ6RZCY533789	Next Service:	114200	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
			D		D	Performance	~		
Key:		$-\infty$				Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect C = crack						Transmission			
						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		
"= decais						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S D PT W W S D PT W						Performance	~		
Body Insi	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	depth	of tyre	es)
Add diagnosed inter manifold leaking air did smoke test.						Left front 6.0		.0	mm
						Right front	6	6.0 m	
						Left rear	3	3.0 n	
Conditions During Body Inspection: Dry						Right rear	3.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments FWD Both rear tyres wearing on outside tread						Suspension			
						Suspension performance	~		
						Steering performance	~		
Centre armrest broken .						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights		~	
Correcto						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ord Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Small headlights not working,						Window winder RR	~		
Foult codes P020200 pylinder 2 P 020200 pylinder 2 P02000 random / mylticla					Rear view mirrors	~			
Fault codes P030300 cylinder 3, P 030200 cylinder 2,P03000 random/ multiple   Misfire,P010600 manifold abs ,pressure or bar . 01272000 central air flap motor   00457:013 vehicle electrical system module. C108000 left/ right hand switch   Road Conditions During Test Drive: Dry						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
						Reversing camera			~
Inspected by: Marlon Espena Date: 04 Sep 2024									

Name: .....