


<b>Make:</b> Toyota	<b>Model:</b> Hiace	<b>Body Style:</b> Van
<b>Year:</b> 2009	<b>Registration:</b> MAN766	<b>Reg Expiry:</b> 03 Apr 2025
<b>WoF Expiry:</b> 28 Mar 2025	<b>Odometer:</b> 236,329 Kms	<b>Good No:</b> 26213932
<b>VIN:</b> 7AT0H60FX18010786	<b>Next Service:</b> 246,336km	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- \* = decals
- SC = stone chips
- W = significant scuffs



**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

- |                                 |  |
|---------------------------------|--|
| Tow hook cover missing.         | Small dent in l/h roof gutter.             |
| Rear reverse mirror removed.    | Paint stains on rear bumper & side skirts. |
| Right wing mirror cover broken. | Jack missing.                              |
| Chipped windscreen.             |  |

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

**Interior Comments**

Seats	Ripped drivers seat, stains.
Carpets	Hole on drivers side.
Panels	Paint stains, scratches & scuffs.
Dashboard	Paint stains, steering wheel worn.

**General Comments**

Petrol auto Hiace van

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	9.0	mm	
Right front	9.0	mm	
Left rear	3.0	mm	
Right rear	3.0	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Daryll Timms

Date: 31 Jul 2024

I have read and understood this condition guide. Name: ..... Signature: .....