

Report ID: 26,224,976 Version: 1 06 Aug 2024 Created:

Make:	Alfa Romeo	Model:	Giulietta	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2015	Registration:	JLK469	Reg Expiry:	26 Nov 2024	Engine	•		
WoF Expiry:	06 Aug 2025	Odometer:	66,352 Kms	Good No:	26224976	Oil level	~		
VIN:	ZAR94000007376229	Next Service:	76,000 Kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	V		
Key:		-0		-01-		Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust	scw bla			ZIS	HIL	Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				게	CV joints	~		
* = decals	- Ole			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W PT P						Performance	~		
		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			<u> </u>
						Left front 8 mm			
						Right front			mm
						Left rear			
						Right rear			mm mm
Conditions During Body Inspection: Dry						Spare	5.7		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	j					Suspension performance	~		
						Steering performance	~		
Shock absorber							~		
Air Conditioning / Heater									
Interior Comments						Operation Electrical / Accessories			
Good									
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General (Comments					Window winder FR	~		<u> </u>
	<u>comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
CD (basic test only)									~
Number of keys							2		
Road Conditions During Test Drive: Dry Central locking							~		<u> </u>
Engine Timing Mechanism: Cambelt Sat Nav (basic test only)							~		<u> </u>
Suidence of Cam Balt Donle comparts - Muse Kings 52,222							~		<u> </u>
Evidence of Cam Belt Replacement: Yes Kms: 52,332									~
Inspected by: Hoani Saunders Date: 05 Aug 2024									

I have read and understood this condition guide.

Name:

Signature: