

Basic Vehicle Condition Guide

Report ID: 26,233,998


Version: 2

Created: 11 Nov 2024

Make: Model: Holden Colorado **Body Style:** Utility Year: 2013 Registration: GSK411 Reg Expiry: 17 Feb 2025 WoF Expiry: **Odometer:** 25 Mar 2025 274,519 Kms **Good No:** 26233998 VIN: MMU148MH0DH6619 **Next Service:** 284000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front bumper damaged Holden badge missing Minor stone chip on the windscreen Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Four wheel drive

Interior Comments					
Seats	Drivers seat torn, Wear and tear.				
Carpets	Good				
Panels	Good				
Dashboard	Good				

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: No

Kms:

Inspected by: Jaykib Collins Date: 12 Aug 2024

Name:

	Create	u: ı	I NOV 2	2024			
]		Pass	Fail	N/A			
	Engine	•	•	•			
	Oil level	~					
	Smoke & fumes	~					
1	Performance	~					
	Noise	~					
	Cooling System			1			
	Coolant condition	~					
	Performance	V V					
	Radiator / Hoses (visual)	~					
	Transmission						
	Operation	~					
	Noise	~					
	Clutch			~			
	CV joints	~					
ĺ	Wheel bearings	~					
	Brakes						
	Performance	~					
ĺ	Hand Brake	<u></u>					
	Tyres (lowest observed tread	l depth	of tyre	<u> </u>			
	Left front 9,0 mm						
	Right front	9.5		mm			
	Left rear	3.5		mm			
1	Right rear	2.5		mm			
	Spare						
	Spare Yes Suspension						
	Suspension performance	V					
	Steering performance	· ·					
	Shock absorbers	•					
	Air Conditioning / Heater						
	Operation		1				
	Electrical / Accessories						
	Head lights	V					
	Tail lights	<i>y</i>					
	Indicators	<i>V</i>					
	Dashboard warning lights	<i>y</i>					
	Wipers (front & rear)	~					
	Window winder FL	V V V V V					
	Window winder FR	<i>y</i>					
	Window winder RL	1/					
ĺ	Window winder RR	<i>y</i>					
	Rear view mirrors	~					
	Radio (basic test only)	<i>v</i>					
ĺ	CD (basic test only)	<i>v</i>					
	Number of keys	1					
l	Central locking	1					
	Remote locking	1/					
	Sat. Nav. (basic test only)			./			
ĺ	Reversing camera	V					
1	c. c. sg carriera						
	Data: 12 Aug 2024						

Signature: