

Report ID: 26,236,241 Version: 1 16 Sep 2024 Created:

Make:	Audi	Model:	A3	Body Style:	Wagon	1		Pass	Fail	N/A
Year:	2014	<b>Registration:</b>		Reg Expiry:		Engine	Engine			1
WoF Expiry:	12 Sep 2025	Odometer:	34,208 Kms	Good No:	26236241	Oil leve	·I	~		
VIN:	WAUZZZ8VXFA01499	Next Service:	44300	Service Histor	r <b>y:</b> No	Smoke	& fumes	~		
						Perforn	nance	~		
	port is not a warranty		for age and mileage	Parts have not	t been dismantled or	Noise		~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional	charge.	Coolan	t condition	V		
						Perforn	nance	V		
Key:		-0		-161-		Radiato	or / Hoses (visual)	V		
S = scratch	STE			NG G	Tan	Transmi				1
D = dent R = rust	HA			715	HIV	Operat	ion	~		
PT = paint defe	ect NP	IT I		$\left( \left\  \right\rangle \right)$		Noise		V		
C = crack				$\square$		Clutch				~
P = pin dent	HIG				7414	CV join	ts	r		
* = decals	- Alt			- John		Wheel	bearings	V		
SC = stone chips W = significant scuffs						Brakes				
W = significant		$\neg \otimes$				Perforn	nance	V		
Padulaci	action Commonts	Note: son	ne defects & blemishes	s may not be dis	played in the diagram	Hand B	rake	~		
<u>bouy insp</u>	pection Comments					Tyres (lo	west observed tread	d depth	of tyre	es)
						Left fro	nt		7	mm
						Right fr	ont		7	mm
						Left rea			7	mm
Conditions During Body Inspection:						Right re	ear		7	mm
Conditions During body inspection.						Spare No				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspen	sion performance	V		
							g performance	~		
						Shock a	absorbers	V		
						Air Cond	litioning / Heater			I
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Average					Head li	ghts	V		
	Good					Tail ligh	nts	r		
Carpets						Indicate		~		
Panels	Good					Dashbo	bard warning lights	~		
	, Good						(front & rear)	~		
Dashboa	ird					Window	w winder FL	~		
	ľ					Windov	w winder FR	~		
General Comments					Window	w winder RL	~			
						Window	w winder RR	~		
						Rear vie	ew mirrors	~	-	
						Radio (	basic test only)	~		
						CD (bas	sic test only)	~		
						Numbe	er of keys	2		1
Road Conditions During Test Drive: Dry						Central	locking	~		
,						Remote	elocking	~		
Engine Timing Mechanism: Cambelt						Sat. Na	v. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:							ng camera	~		1
Evidence	of Calli Bell Replac	ement. p		i di li di		Reversi	ng camera			
	d by: Mark Robertson					Reversi	Date: 16 Sep 20			

I have read and understood this condition guide.

Name: .....

Signature: .....