

| | | |
|--------------------------------|------------------------------|--------------------------------|
| Make: Holden | Model: Barina | Body Style: Hatchback |
| Year: 2012 | Registration: GLM312 | Reg Expiry: 01 Oct 2024 |
| WoF Expiry: 28 Jun 2025 | Odometer: 175,213 Kms | Good No: 26241556 |
| VIN: KL3TA48E9CB123625 | Next Service: | Service History: Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs

Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments
Front bumper misaligned
Left sill dented

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments
Engine oil leak

Interior Comments

| | |
|-----------|---------|
| Seats | Average |
| Carpets | Average |
| Panels | Poor |
| Dashboard | Poor |

General Comments
Creamy liquid in coolant reservoir
Partial service history
Hard brake pedal
Rattle and engine misfire
Jerky transmission

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A |
|-----------------------------------------------------|------|------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | | ✓ | |
| Performance | | ✓ | |
| Noise | | ✓ | |
| Cooling System | | | |
| Coolant condition | | ✓ | |
| Performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | | ✓ | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | | ✓ | |
| Hand Brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | 3 | mm | |
| Right front | 4 | mm | |
| Left rear | 6 | mm | |
| Right rear | 4 | mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. Nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

Inspected by: Sione Mae Date: 15 Aug 2024

I have read and understood this condition guide. Name: Signature: