

Report ID: 365 Version: 1 26 Sep 2024 Created:

Make: Holden Model: Cruze Body Style: Sedan	Pass Fail N/A
Year: 2014 Registration: HPC928 Reg Expiry: 30 Jul 2025	5 Engine
WoF Expiry: 29 Jun 2025 Odometer: 62,734 Kms Good No: 26248146	Oil level 🖌
VIN: 6G1PD5EMXEL921543 Next Service: Service History:	Smoke & fumes 🖌
	Performance 🖌
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been disma	antled or Noise
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor reco	
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	Coolant condition
	Performance 🖌
key:	Radiator / Hoses (visual)
S = scratch D = dent	Transmission
R=rust SSC AR	S Operation 🖌
PT = paint defect	Noise 🖌
C = crack	S Clutch 🖌
P = pin dent	CV joints 🖌
*= decais	Wheel bearings 🖌
SC = stone chips W = significant scuffs	Brakes
	Performance 🖌
Body Inspection Comments Note: some defects & blemishes may not be displayed in the	diagram Hand Brake 🖌
	Tyres (lowest observed tread depth of tyres)
	Left front 7 mm
	Right front 7 mm
	Left rear 7 mm
Conditions During Body Inspection:	Right rear 7 mm
	Spare N/A
Under Carriage & Under Bonnet Inspection Comments	Suspension
	Suspension performance 🖌
	Steering performance 🖌
	Shock absorbers 🖌
	Air Conditioning / Heater
	Operation 🖌
Interior Comments	Electrical / Accessories
Seats Average	Head lights 🖌
Average	Tail lights 🖌
Carpets	Indicators 🖌
Panels Average	Dashboard warning lights 🖌
Average	Wipers (front & rear)
Dashboard	Window winder FL 🖌
	Window winder FR 🖌
<u>General Comments</u>	Window winder RL 🖌
	Window winder RR 🖌
	Rear view mirrors
	Radio (basic test only) 🖌
	CD (basic test only)
	Number of keys 2
Road Conditions During Test Drive: Dry	Central locking 🖌
,	Remote locking
Engine Timing Mechanism: Timing Chain	Sat. Nav. (basic test only)
Evidence of Cam Belt Replacement: Not Applicable Kms:	Reversing camera 🗸 🗸
Inspected by: Willy	Date: 26 Sep 2024

I have read and understood this condition guide.

Name:

Signature: