

Report ID: 26,248,649 Version: 2 27 Aug 2024 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2006	Registration:	DJN965	Reg Expiry:	03 Oct 2024	Engine			1
WoF Expiry:	20 Dec 2024	Odometer:	333,444 Kms	Good No:	26248649	Oil level		~	
VIN:	MR0EX12G802007382	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		-
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	nical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		1
						Performance	~		
Key:	S SC	-0		-01-		Radiator / Hoses (visual)		~	-
S = scratch						Transmission			
D = dent R = rust	s sc			715		Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+		Clutch	~		
P = pin dent					세비	CV joints	~		
* = decals	s sc 916			- NL	ETP-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC						Performance	~		
		Note: som	ne defects & blemishes	s may not be disr	blaved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftyre	 es)
No jack equipment. Body works poor condition						Left front 6.0 mm			
						Right front			mm
						Left rear		.0	mm
								2.0	
Conditions During Body Inspection: Dry						-			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	mum. underbody surfac			n		· · · · · · · · · · · · · · · · · · ·			T
	mam. underbody sunde	e rust. On reaks.				Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation	~		
Poor						Electrical / Accessories			
Seats						Head lights	~		<u> </u>
Carpets	Poor					Tail lights	~		<u> </u>
	scratches	scuffs marks				Indicators	~		┿
Panels	Sciateries					Dashboard warning lights	~		<u> </u>
Dashboa	Poor					Wipers (front & rear)	~		──
						Window winder FL	~		<u> </u>
Concret	Commonts					Window winder FR	~		<u> </u>
<u>General Comments</u> Engine light on Cup holders missing. Glovebox missing.					Window winder RL	~		<u> </u>	
			······ 3·			Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking			~
Engine T	ming Machaniana	T:	Chain			Remote locking		~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Incoacte	d by: Gary Adams					Date: 19 Aug 20	24		
inspecte	a by. Gury Additis					Date. 19 Aug 20			

I have read and understood this condition guide.

Name:

Signature: