

Report ID: 26,259,543 Version: 1 29 Aug 2024 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	Registration:	LAE886	Reg Expiry:	04 May 2025	Engine	1 455	i un	
	26 Jan 2025	Odometer:	220,743 Kms	Good No:	26259543	Oil level	~		
VIN:	JM0GH105100112827			Service History		Smoke & fumes	~		
	5///041105100112027		223,000		. 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
						Coolant condition	~		
Key:	S PT		S D R SC S D R S		S D R W	Performance	~		
S=scratch						Radiator / Hoses (visual)			
D = dent									
R = rust						Operation	~		
PT = paint def	ect M				S R PT SC	Noise	~		
C = crack	III					Clutch			~
P = pin dent * = decals SC DR						CV joints	~		
* = decals SC = stone chips						Wheel bearings	3		
W = significant scuffs						Brakes			
	S PT		S R PT C SC S PT W		S PT P	Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Minor Stone Chips Windscreenn						Tyres (lowest observed tread	d depth	of tyre	2S)
Water in Boot						Left front	3.	0	mm
Boot Button On Boot N/W Headlights Faded						Right front	4.	0	mm
Left Mirror Outer Cracked						Left rear	4.	0	mm
Conditions During Body Inspection: Wet						Right rear	4.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil Seepage						Suspension performance	~		
Inner CV Boots Leaking Rear Sub Frame Mounting Brackets Surface Rust						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Drivers Sea	at Worn				Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		<u> </u>
	A					Wipers (front & rear)	~		+
Dashboa	rd Average					Window winder FL	~		+
						Window winder FR	~		+
General Comments					Window winder RL	~		+	
Knocking Noise from Dash						Window winder RR	~		<u> </u>
Rough Idle Spare Tyre Not Secured, Tools w/ No Jack						Rear view mirrors	~		+
Spare Tyre		JUCK				Radio (basic test only)	~		
						CD (basic test only)	~		+
						Number of keys	2		L
Road Conditions During Test Drive: Wet						Central locking	2		
Road Con	aitions During Test	Drive:	Wet			Remote locking			
Engine Ti	ming Mechanism:	Timing (Chain			-	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
						Reversing camera			~
Inspected by: Samuel Weir Date: 29 Aug 2024									

I have read and understood this condition guide.

Name:

Signature: