

Report ID: 26,263,482 Version: 1 28 Aug 2024 Created:

Make:	Mercedes-Benz	Model:	CLK	Body Style:	Convertible		Pass	Fail	N/A
Year:	2000	Registration:	QJU728	Reg Expiry:	04 Oct 2024	Engine	1 435	' un	14/14
	16 Dec 2024	Odometer:	179,864 Miles	Good No:	26263482	Oil level	~		
VIN:	WDB2084702T071982			Service History		Smoke & fumes	~		
	1122200 17 02107 1902		171,000			Performance	~		
	oort is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:	S R P SC	-0	S D R SC		S R SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation	~		
R = rust						Noise	~		
PT = paint defect C = crack						Clutch			~
P = pin dent						CV joints			~
* = decals SRSC 919 SR						Wheel bearings	~		
SC = stone chips						Brakes	v		
W = significant scuffs S D SC S D SC S D SC S PT						Performance	~		
		Note: som		s may not be disn	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								oftyre	) )
Minor Stone Chips Windscreen Bonnet Badge in Glovebox						Tyres (lowest observed tread depth of tyres)Left front2.0 mm			
Left Mirror Indicator Cracked									
Right Mirror Delaminating, Headlight Fade - Expected for Age & Mileage						Right front Left rear		.5	mm
								.5	mm
Conditions During Body Inspection: Dry						Right rear 5.0 mm   Spare Yes			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
Oil, Coolant & Diff Leak						Suspension performance			
Front Tyres						Steering performance	<b>v</b>		
						Shock absorbers	~		
							~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good									
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights		~	
Dashboa	rd Faded					Wipers (front & rear)	~		
						Window winder FL	<b>v</b>		
General	Comments					Window winder FR Window winder RL	~		
Speedometer Screens Faulty							~		
ABS and ESP Warning Messages						Window winder RR	~		
Body Flex Over Speed Bumps Minor Vibrations at Speed with Grinding Noise Before Takeoff					Rear view mirrors	<b>v</b>			
Left Window Doesn't Self Close, Leaves Window Cracked Open						Radio (basic test only)	~		
**Private Consignment - Sale on Behalf**						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)		~	<u> </u>
		ciriciti. N		11113.		Reversing camera			~
Inspected	d by: Samuel Weir					Date: 26 Aug 20	24		

I have read and understood this condition guide.

Name: .....

Signature: .....