

Basic Vehicle Condition Guide

Report ID: 26,263,794


Version: 1

Created: 13 Sep 2024

Make: Model: Haval H2 **Body Style:** SUV Year: 2020 Registration: MUK642 Reg Expiry: 14 Dec 2024 **WoF Expiry: Odometer:** 23 Aug 2025 45,401 Kms **Good No:** 26263794 VIN: LGWEE4A47LH91452(Next Service: 55000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Drives okay, Freshly serviced

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara Date: 26 Aug 2024

Name:

	Fail	N/A
Pass	Ган	IN/A
./		
•		
•/		
•/		
./		
•		
<i>y</i>		
_		
V		
<i>y</i>		
_		1
~		ľ
·		
V		
~		
d depth	of tvre	L es)
		mm
		mm
		mm
-		mm
~		
~		
~		
ı		
~		
	ı	
V		
\(\times \) \(\t		
\(\times \) \(\t		
V V V V V V		
V V V V V		
\(\times \) \(\t		
V V V V V		
V V V V V		
V V V V V V		
V V V V V V		
V V V V V V V		
V V V V V V V		
	3	V

Signature: