

Basic Vehicle Condition Guide

Report ID: 26,265,349

Pass

1

/

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL

Spare

Coolant condition Performance

Radiator / Hoses (visual)

01 Sep 2024 Created:

Fail

N/A

1

mm

mm

mm

 mm

5

4

1

/


/

Yes

Make: Hyundai Model: Tucson **Body Style:** SUV Year: 2007 Registration: DTR358 **Reg Expiry:** 13 Dec 2024 WoF Expiry: **Odometer:** 21 Jun 2025 134,949 Kms **Good No:** 26265349 VIN: KMHJN81BR7U572454 Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Under Carriage & Under Bonnet Inspection Comments

Interior Comments	5
Seats	Good
Carpets	Good
Panels	Average
Dashboard	Good

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Oneplus East

Evidence of Cam Belt Replacement:

Kms:

Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera 1 24 Aug 2024 Date: Signature:

I have read and	understood this	condition	auide.

Name			