

Basic Vehicle Condition Guide

Report ID: 26,269,362

Pass

1

V

/

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Coolant condition
Performance

Radiator / Hoses (visual)

Created: 07 Oct 2024


Fail

N/A

Make: Subaru Model: Legacy **Body Style:** Sedan Year: 2006 Registration: KPL518 **Reg Expiry:** 19 May 2025 **WoF Expiry: Odometer:** 16 Sep 2025 73,372 Kms **Good No:** 26269362 VIN: 7AT0GF0BX17055571 **Next Service:** 78000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>s</u>
Seats	Poor
Carpets	Poor
Panels	Poor
Dashboard	Poor

General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

John Jones

Evidence of Cam Belt Replacement: No Kms:

Operation Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm 5.0 Right front 5.0 mm Left rear 7.0 mm Right rear 7.0 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) / Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) Reversing camera

I have read and understood this condition guide.

_	
Vame [.]	

30 Aug 2024

Date: