

Report ID: 26,270,177 Version: 2 Created: 04 Sep 2024

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2010	Registration:	NHM895	Reg Expiry:	30 Sep 2024	Engine		-	<u> </u>
WoF Expiry:	05 Aug 2025	Odometer:	112,000 Kms	Good No:	26270177	Oil level	~		
VIN:	WVWZZZ1KZBW0455	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		c			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			1
						Performance	~		
Key:	sc	-0	sc sc		SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	IS GIR			The	S SC W	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack				+	SC	Clutch			~
P = pin dent	Ho					CV joints	~		
* = decals	sc pp			AL.	ELIP S SC	Wheel bearings	~		
SC = stone chi	ps U	20		JAL)	& <u> </u>	Brakes	V		
W = significant scuffs S SC S SC S SC S SC SC SC						Performance			1
		Note: com	ne defects & blemishes	may not be disc		Hand Brake	く く		
Body Insp	pection Comments	Note. son	le délects & blemisnes	illay not be disp	layed in the diagram		•	~ f to	<u> </u>
					Tyres (lowest observed tread depth of tyres)				
						Left front		.6	mm
						Right front	4		mm
						Left rear	5.1		mm
Conditions During Body Inspection: Dry						Right rear	5.3		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
No underbody inspection						Suspension			
No underbo	buy inspection					Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
marks						Electrical / Accessories			
Seats	marks					Head lights	~		
Carpets	wear hole	s, marks				Tail lights	~		<u> </u>
	woor					Indicators	~		<u> </u>
Panels	wear					Dashboard warning lights	~		<u> </u>
Dashboa	Good Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	2		
			·			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera		~	
Inspected by: Melissa Wilson Date: 04 Sep 2024									

I have read and understood this condition guide.

Name:

Signature: