

| Make: | Hyundai | Model: | 130 | Body Style: | Hatchback | | | Pass | Fail | N/A | |
|--|--------------------------|----------------------|------------------------|--------------------|-----------------------|--------|--|----------|----------|---------------------|--|
| Year: | 2011 | Registration: | GBW357 | Reg Expiry: | 29 Sep 2024 | | Engine | | | 1 | |
| WoF Expiry: | 06 Mar 2025 | Odometer: | 160,120 Kms | Good No: | 26277915 | | Oil level | ~ | | | |
| VIN: | KMHDC51EMBU32749 | Next Service: | 170,000 | Service Histor | r y: Yes | | Smoke & fumes | ~ | | | |
| | | | | | | | Performance | ~ | | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | t been dismantled or | | Noise | r | | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | | Cooling System | | | | |
| a full mechan | ical inspection prior to | purchase and t | his can be arranged fo | or an additional | charge. | | Coolant condition | ~ | | | |
| | | | | | | 1 | Performance | ~ | | | |
| Key: | S | -0 | | -161- | | | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | | | | | | | Transmission | - | | | |
| D = dent | SC DI | | | 715 | EII S |] | Operation | ~ | | | |
| R = rust PT = paint defe | | | | \prod | JUIL | | Noise | ~ | | | |
| C = crack | | | | + | |] | Clutch | | | ~ | |
| P = pin dent | | | | | | | CV joints | ~ | | | |
| * = decals | sc 916 | | | - NL | ELTP IS | 1 | Wheel bearings | ~ | | | |
| SC = stone chips | | | | | | Brakes | | | | | |
| W = significant scuffs SC D D D | | | | | | | Performance | ~ | | | |
| | | Note: son | ne defects & blemisbes | may not be disr | played in the diagram | | Hand Brake | ~ | | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | | | • | of tyre | (ک ^ر | |
| · | | | | | | | Tyres (lowest observed tread depth of tyres) Left front 3.5 mm | | | | |
| | | | | | | | Right front | | .5 .5 | mm | |
| | | | | | | | Left rear | | | mm | |
| | | | | | | 7 | Right rear | 2.0 | | mm | |
| Conditions During Body Inspection: Dry | | | | | | | Spare | | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | | Spare Yes Yes | | | | |
| <u></u> | | | | | | | Suspension performance | ~ | | | |
| | | | | | | | Steering performance | ~ | | | |
| | | | | | | | Shock absorbers | ~ | | | |
| | | | | | | | Air Conditioning / Heater | V | | | |
| | | | | | | | Operation | | | T | |
| Interior Comments | | | | | | | Electrical / Accessories | ~ | | | |
| | Good | | | | | | | | | | |
| Seats | | | | | | | Head lights | v | | | |
| Carpets | Good | | | | | | Tail lights | ~ | | | |
| | Good | | | | | | Indicators | ~ | | | |
| Panels | | | | | | | Dashboard warning lights | • | | <u> </u> | |
| Dashboa | rd Good | | | | | | Wipers (front & rear) | ~ | | | |
| | | | | | | | Window winder FL | ~ | | | |
| General Comments | | | | | | 1 | Window winder FR | • | | | |
| | | | | | | | Window winder RL | ~ | | - | |
| | | | | | | | Window winder RR | ~ | | | |
| | | | | | | | Rear view mirrors | ~ | | ── | |
| | | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | | CD (basic test only) | ~ | | | |
| | | | | | | | Number of keys | 2 | 1 | | |
| Road Con | ditions During Test | t Drive: | Dry | | | | Central locking | ~ | | | |
| Engine Ti | ming Mechanism | Cambel | | | | 1 | Remote locking | ~ | | <u> </u> | |
| | | | | | | | Sat. Nav. (basic test only) | | | ~ | |
| Evidence of Cam Belt Replacement:YesKms:97,979 | | | | | | | Reversing camera | | | ~ | |
| Inspected by: Reuben Harvey | | | | | | | Date: 03 Sep 2024 | | | | |

I have read and understood this condition guide.

Name:

.

Signature: