

Basic Vehicle Condition Guide

Report ID: 26,285,439


Version: 1

Created: 19 Sep 2024

Make: Model: Holden Cruze **Body Style:** Hatchback Year: 2012 Registration: MJE705 Reg Expiry: 05 Mar 2025 WoF Expiry: **Odometer:** 20 Dec 2024 164,014 Kms **Good No:** 26285439 VIN: 6G1PD6E52CL648786 Next Service: 170888 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Minor oil leak,

| Interior Comments | | | |
|-------------------|--------------------------|--|--|
| Seats | wear,worn,minor stains , | | |
| Carpets | wear,minor stains , | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Drives okay,

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Donovan Matara

Kms: 147,000

| | Pass | Fail | N/A | | |
|------------------------------|---------------------------------------|---------|-----|--|--|
| Engine | | ı | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | ~ | | | | |
| Performance | <i>V V</i> | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | V | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | ~ | | | | |
| CV joints | \(\times \) | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | |
| Left front | 2 | .8 | mm | | |
| Right front | 2 | .4 | mm | | |
| Left rear | 2.4 | | mm | | |
| Right rear | 3.0 | | mm | | |
| Spare | Yes | | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | | ~ | | | |
| Electrical / Accessories | | | | | |
| Head lights | / | | | | |
| Tail lights | ~ | | | | |
| Indicators | \(\triangle \) | | | | |
| Dashboard warning lights | | | | | |
| Wipers (front & rear) | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | V | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 2 | | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | ~ | | |
| | | | | | |

I have read and understood this condition guide.

Name:

Signature:

04 Sep 2024