

Basic Vehicle Condition Guide

Report ID: 26,285,711


Version: 1

Created: 05 Sep 2024

Make: Model: Honda Odyssey **Body Style:** Wagon Year: 2009 Registration: QRQ204 Reg Expiry: 11 Jul 2025 WoF Expiry: **Odometer: Good No:** 20 Jul 2025 68,500 Kms 26285711 VIN: 7AT08G61X24021083 **Next Service:** 78551 / 05.09.2025 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Motor Crew Date: 05 Sep 2024

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\triangle \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	V		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	6	.4	mm
Right front	4.8		mm
Left rear	6.4		mm
Right rear	6.9		mm
Spare		N/A	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		!	
Operation	~		
Electrical / Accessories			•
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	✓ ✓		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

Signature: