

Basic Vehicle Condition Guide

Report ID: 26,285,908


Version: 1

Created: 26 Nov 2024

Make: Model: Mazda Atenza **Body Style:** Wagon Year: 2013 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 25 Nov 2025 144,631 Kms 26285908 VIN: 7AT0C139X24101308 Next Service: 154,000 kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | |
|-------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Dean Sinclair 26 Nov 2024 Inspected by: Date:

Name:

| | Pass | Fail | N/A | |
|------------------------------|--------------|---------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\times \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | |
| Left front | 6 | | mm | |
| Right front | 6 | | mm | |
| Left rear | 6.5 | | mm | |
| Right rear | 3 | | mm | |
| Spare | N/A | | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | \(\sigma \) | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | \(\times \) | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | \(\times \) | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 1 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |
| L | | | | |

Signature: