

Basic Vehicle Condition Guide

Report ID: 26,291,094

Pass

Version: 2

Created: 22 Nov 2024


Fail

N/A

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2010 Registration: JEZ931 Reg Expiry: 16 Sep 2024 WoF Expiry: **Odometer:** 01 Oct 2025 313,813 Kms **Good No:** 26291094 VIN: MMAJNKB40AD01573 Next Service: 324,000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	5
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Drivers seat adjustment switch button missing. No key/lock for canopy.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms:

Inspected by: Reuben Harvey Date: 20 Sep 2024

Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System	•	•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•		
Operation	~		
Noise	\(\times \)		
Clutch	~		
CV joints	~		
Wheel bearings	~		
Brakes	•		
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	9	.5	mm
Right front	9.5		mm
Left rear	12.0		mm
Right rear	12.0		mm
Spare		Yes	
Suspension	•		
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	v v		
Dashboard warning lights			
Wipers (front & rear)	\(\times \)		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~

I have read and understood this condition guide.

Name [,]			

313,816