

Report ID: 26,299,044 Version: 1 07 Oct 2024 Created:

Make:	Hyundai	Model:	lload	Body Style:	Van		Pass	Fail	N/A
Year:	2013	Registration:	HNG365	Reg Expiry:	08 Sep 2024	Engine			
WoF Expiry:	24 Sep 2025	Odometer:	211,351 Kms	Good No:	26299044	Oil level	~		
VIN:	KMFWBX7KLDU58834	Next Service:	215000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	P SC	-0	SD* SD*	-01-	S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	SDCSC			715	HIL	Operation	~		
PT = paint defe	ect NP	F		$\left[\left(\right) \right]$		Noise	~		
C = crack					S SC	Clutch	~		
P = pin dent	HID				거네	CV joints	~		
* = decals	SP*SC 916			-NG	BID SD*	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S D * * SC S D						Performance	~		
Dedular		Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
Nudge bar front and rear bumper's ,roof racks,						Left front			
						Right front	6.		mm
						Left rear	5.		mm
Conditio	ns During Body Insi	nection:	Dry			Right rear	4.		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Fair					Head lights	~		
<u></u>	Fair					Tail lights	~		
Carpets	i un					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	·					Window winder FR	~		
General Comments						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		•
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Donovan Matara Date: 11 Sep 2024									

I have read and understood this condition guide.

Name:

Signature: