

Basic Vehicle Condition Guide

Report ID: 26,299,173


Version: 1

Created: 03 Oct 2024

Make: Model: Toyota Hiace **Body Style:** Minibus Year: 2016 Registration: JYC166 Reg Expiry: 08 Apr 2025 WoF Expiry: **Odometer: Good No:** 08 Oct 2025 271,814 Kms 26299173 VIN: **Next Service:** JTFST22PX00028093 281000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

Genera	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt No

Evidence of Cam Belt Replacement:

Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	V		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	7.5		mm
Right front	8.9		mm
Left rear	4.5 m		mm
Right rear	4.4		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	\(\tau \)		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	3	1	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Poversing camera		1	1

Reversing camera

Signature:

13 Sep 2024 Inspected by: Donovan Matara

Name: