

## **Basic Vehicle Condition Guide**

Report ID: 26,302,932

**Pass** 

1

~

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

**Transmission** 

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

23 Sep 2024 Created:

Fail

~

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

3.0

3.0

3.0

3.0

1

/

/

/

1

1


2

Yes

Make: Model: Holden Astra **Body Style:** Hatchback Year: 2017 Registration: QTW662 **Reg Expiry:** 27 Feb 2025 WoF Expiry: **Odometer:** 07 Mar 2025 74,669 Kms **Good No:** 26302932 VIN: W0LBF6EH4HG04338( Next Service: 80000 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

## **General Comments**

Drives okay but has a squeking noise coming from engine bay and been told it needs a new PCV valve

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism: Timing Chain** 

I have read and understood this condition guide.

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Date: 13 Sep 2024 Inspected by: Donovan Matara

	<u>'</u>
Name:	Signature:
Name:	Signature: