

Report ID: 26,304,378 Version: 1 01 Oct 2024 Created:

| Make: Audi Model: Q3 Body Style: Wagon |] | Pass I | ail N/A |
|--|------------------------------|----------|----------|
| Year: 2015 Registration: Reg Expiry: | Engine | | |
| WoF Expiry: Odometer: 65,466 Kms Good No: 26304378 | Oil level | ~ | |
| VIN: WAUZZZ8U9FR02601 Next Service: 75000 Service History: No | Smoke & fumes | ~ | |
| | Performance | ~ | |
| Note: This report is not a warranty | Noise | ~ | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | Cooling System | v | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | Coolant condition | ~ | |
| | Performance | ~ | |
| Key: | Radiator / Hoses (visual) | ~ | |
| S = scratch | Transmission | V | |
| D = dent | | | |
| R = rust | Operation | ~ | |
| PT = paint defect | Noise | ~ | |
| C = crack P = pin dent | Clutch | | ~ |
| *= decals | CV joints | ~ | |
| SC = stone chips | Wheel bearings | ~ | |
| W = significant scuffs | Brakes | | |
| | Performance | ~ | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | Hand Brake | ~ | _ |
| | Tyres (lowest observed tread | depth of | f tyres) |
| | Left front | 6 | mm |
| | Right front | 7.1 | mm |
| | Left rear | 6.2 | mm |
| Conditions During Body Inspection: Dry | Right rear | 6.5 | mm |
| | Spare | | No |
| Under Carriage & Under Bonnet Inspection Comments | Suspension | | |
| | Suspension performance | ~ | |
| | Steering performance | ~ | |
| | Shock absorbers | ~ | |
| | Air Conditioning / Heater | | |
| | Operation | ~ | |
| Interior Comments | Electrical / Accessories | | |
| Seats Good | Head lights | ~ | |
| Good | Tail lights | ~ | |
| Carpets | Indicators | ~ | |
| Panels Good | Dashboard warning lights | ~ | |
| Good | Wipers (front & rear) | ~ | |
| Dashboard | Window winder FL | ~ | |
| | Window winder FR | ~ | |
| General Comments | Window winder RL | ~ | |
| | Window winder RR | ~ | |
| | Rear view mirrors | ~ | |
| | Radio (basic test only) | ~ | |
| | CD (basic test only) | ~ | |
| | Number of keys | 2 | |
| Road Conditions During Test Drive: Dry | Central locking | ~ | |
| | Remote locking | ~ | |
| Engine Timing Mechanism: Timing Chain | Sat. Nav. (basic test only) | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | Reversing camera | ~ | |
| Inspected by: Mark Robertson Date: 01 Oct 2024 | | | |

I have read and understood this condition guide.

Name:

Signature: