

Report ID: 26,307,023 Version: 1 25 Oct 2024 Created:

Make:	Mazda	Model:	Axela	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2018	Registration:		Reg Expiry:		Engine	I	<u> </u>	I	
WoF Expiry:	18 Oct 2025	Odometer:	96,529 Kms	Good No:	26307023	Oil level	~			
VIN:	7AT0C13JX24201193	Next Service:	106,550kms	Service Histor	y: No	Smoke & fumes	~			
			- -			Performance	~			
	port is not a warranty	avation is made	for one and miles as	Danta hava nat	heen dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.										
						Coolant condition	nt condition			
						Performance	~			
Key:		-0		-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	- HIE			TIN		Operation	~			
R = rust PT = paint defe				$\left[\right] \left[\right]$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HIG				74114	CV joints	~			
* = decals	- Ole			The		Wheel bearings	~			
SC = stone chips						Brakes				
W = significan	t scutts					Performance	~			
Podulas"	action Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)				
						Left front	, ,	7	mm	
						Right front		7	mm	
						Left rear	6	5	mm	
Conditions During Body Inspection: Dry						Right rear	e	6 mm		
						Spare	N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	1			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
General Comments					Window winder RL	~				
Hybrid Axel	la sedan.					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry Central locking							~			
	-					Remote locking	~			
-	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected	Inspected by: Daryll Timms Date: 25 Oct 2024									

I have read and understood this condition guide.

Name:

Signature: