

| | | | - | |
|--|---|--|--|--------|
| | SD SPSC SD | Performance | ~ | |
| Ney. | | Radiator / Hoses (visual) | ~ | |
| S = scratch | | Transmission | | |
| D = dent R = rust S So | | Operation | ~ | |
| PT = paint defect | | Noise | ~ | |
| C = crack | S SC | Clutch | ~ | |
| P = pin dent | | CV joints | ~ | |
| * = decals | MIN SD | Wheel bearings | ~ | |
| SC = stone chips | | Brakes | | |
| W = significant scuffs | S SC S SC S SC S D SC | Performance | ~ | |
| Body Inspection | Note: some defects & blemishes may not be displayed in the diagram | Hand Brake | ~ | |
| Body Inspection Comments Nudge bar front bumper ,roof racks,rear bumper nudge bar dented, | | Tyres (lowest observed tread depth of tyres) | | |
| naage sa none samper poor racks, car samper haage sar denea, | | Left front | 2.3 | mm |
| | | Right front | 2.9 | mm |
| | | Left rear | 4.2 | mm |
| Conditions During Body Inspection: Dry | | Right rear | 4.5 | mm |
| | | Spare | Ye | 25 |
| <u>Under Carriage</u> | Suspension | | | |
| Transmission leak,needed oil, | | Suspension performance | ~ | |
| | | Steering performance | ~ | |
| | | Shock absorbers | ~ | |
| | | Air Conditioning / Heater | II | |
| | | Operation | ~ | |
| Interior Comments | | Electrical / Accessories | II | |
| Seats | RF seat ripped,stained, | Head lights | ~ | |
| Carpets | RF floor worn, | Tail lights | ~ | |
| | | Indicators | ~ | |
| Panels | gear stick sock torn, | Dashboard warning lights | ~ | |
| | Average | Wipers (front & rear) | ~ | |
| Dashboard | , neidge | Window winder FL | ~ | |
| | | | | |
| | | Window winder FR | v | |
| General Comme | | Window winder FR Window winder RL | | ~ |
| | e <u>nts</u> keys missing the push button system inside the casing, | | | ~ ~ |
| | | Window winder RL | v | |
| | | Window winder RL Window winder RR | | |
| | | Window winder RL Window winder RR Rear view mirrors | ~ | |
| | | Window winder RL Window winder RR Rear view mirrors Radio (basic test only) | · · · · · | |
| one of the ignition | xeys missing the push button system inside the casing, | Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) | | |
| one of the ignition | | Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys | V V V 2 | |
| one of the ignition | seys missing the push button system inside the casing, | Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking | ✓ ✓ ✓ ✓ 2 ✓ | |
| one of the ignition | seys missing the push button system inside the casing, | Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking Remote locking | ✓ ✓ ✓ ✓ 2 ✓ | |
| one of the ignition Road Conditions Engine Timing M Evidence of Cam | seys missing the push button system inside the casing, b During Test Drive: Dry Mechanism: Timing Chain | Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking Remote locking Sat. Nav. (basic test only) | ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ | |

I have read and understood this condition guide.

Name:

Signature:

Pass

V

V

V

~

Fail

V

N/A

Report ID:
 26,309,764

 Version:
 1

 Created:
 12 Nov 2024