

	Report ID:		26,311,367				
Ę	Version:		1				
	Created:		08 Oct 2024				
		Pass	Fail	N/A			

WoF Expiry:	14 Sep 2025	Odometer:	105,764 Kms	Good No:	26311367		Oil level	~			
VIN:	KPT50B1ESJP013293	Next Service:	115631	Service Histor	y: No		Smoke & fumes	~			
							Performance	~			
	port is not a warranty s a quide only. Consid		for age and mileage	e. Parts have not	been dismantled o	r	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					s	Cooling System					
a fuil mechan	lical inspection prior to	purchase and ti	his can be allanged h		Lilarge.		Coolant condition	~			
	S SC		SC S SC		SC	ור	Performance	~			
Key:		=		5(0)-			Radiator / Hoses (visual)	~			
S = scratch D = dent	ALE.				商	-	Transmission				
R = rust	s sc			710	E SC		Operation	V			
PT = paint def	ect NP	1				_	Noise	V			
C = crack						_	Clutch			~	
P = pin dent	ssc de				2414		CV joints	V			
* = decals		10		70	ED S		Wheel bearings	~			
SC = stone chi W = significan		× (Q)		20	×		Brakes		-1		
W – signinean	SC	- C	SC SC		S SC		Performance	~			
Body Insr	pection Comments	Note: son	ne defects & blemishe	es may not be disp	played in the diagram		Hand Brake	~			
1 .	ce history available	2					Tyres (lowest observed tread	dept	h of tyre	es)	
							Left front		6	mm	
							Right front		6	mm	
							Left rear		8	mm	
Conditio	ns During Body Ins	pection:	Dry			ור	Right rear		8	mm	
		•	•			4	Spare		Yes		
Under Ca	arriage & Under Bo	nnet Inspectio	on Comments				Suspension				
4x4/							Suspension performance	V			
							Steering performance	V			
							Shock absorbers	V			
							Air Conditioning / Heater		.!		
						=	Operation	~			
Interior C	Comments						Electrical / Accessories		4		
Seats	Good						Head lights	~			
	Good						Tail lights	~			
Carpets							Indicators	~			
Panels	Good						Dashboard warning lights	~			
	, Good						Wipers (front & rear)	~			
Dashboa	ard						Window winder FL	~			
						4	Window winder FR	~			
	<u>Comments</u>						Window winder RL	~			
Fair for age	and mileage						Window winder RR	~			
							Rear view mirrors	V			
							Radio (basic test only)	~			
							CD (basic test only)	V			
							Number of keys	1			
Road Con	ditions During Tes	t Drive:	Dry			ן ר	Central locking	~			
			•			4	Remote locking	V			
Engine Timing Mechanism: Timing Chain					Sat. Nav. (basic test only)			~			
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:			Reversing camera	~			
Inspecte	d by: Uriah Pepene						Date: 08 Oct 202	24			

I have read and understood this condition guide.

Name:

.....

Signature: