

Report ID: 26,311,691 Version: 2 04 Dec 2024 Created:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	Registration:	NAL528	Reg Expiry:	22 Oct 2024	Engine			I
WoF Expiry:		Odometer:	164,459 Kms	Good No:	26311691	Oil level	~		
VIN:	MPATFS85JFT006710	Next Service:		Service Histor	y: No	Smoke & fumes	~		
			,			Performance	~		
	port is not a warranty		с I I	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	SRSC	-0	S R P SC S R P SC		S D PT SC	Radiator / Hoses (visual)	~		
S = scratch							ransmission		
D = dent						Operation			
R = rust				10		Noise	~		
PT = paint def C = crack	ect			+	S D R SC	Clutch	•		
P = pin dent	Htc					CV joints			マ マ
* = decals	SRSC DE			AL-	SDRPT	Wheel bearings			V
SC = stone chips							3		
W = significant scuffs S R S R PT P S R SC S D R PT SC						Brakes			
		N				Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Minor Stone Chips Windscreen						Tyres (lowest observed tread depth of tyres)			
						Left front	3.	0	mm
						Right front	3.	0	mm
r						Left rear	5.	0	mm
Conditions During Body Inspection: Dry						Right rear	4.5 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Compete	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Upper Glovebox Lid Jammed Turbo						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		-
Inspected by: Samuel Weir Date: 25 Sep 2024									

I have read and understood this condition guide.

Name:

Signature: