

Report ID: 26,322,093 Version: 3 Created: 02 Oct 2024

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	Registration:	QRS951	Reg Expiry:	09 Jan 2025	Engine	I	<u> </u>	1
WoF Expiry:	16 Oct 2025	Odometer:	262,281 Kms	Good No:	26322093	Oil level	~		
VIN:	MMU148MH0DH6402	Next Service:	272,000	Service Histor	y: No	Smoke & fumes	~		
			•			Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Darts have not been dismontiad as						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	S PT SC	-0	S R P SC W S R P SC		S D R PT SC	Radiator / Hoses (visual)	~		
S = scratch							ransmission		
D = dent	S D SC			The	BID SW	Operation	~		
R = rust				$\prod_{i=1}^{n}$	JHIH	Noise	~		
PT = paint def C = crack				+	S R SC	Clutch	~		
P = pin dent	40	KI			JUII —	CV joints			
* = decals	SDRSC PR			AL.	SRPT		~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs S PT SC S R P SC W S D W S D R						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		Ļ
Left Step Damaged						Tyres (lowest observed tread depth of tyres)			
Minor Stone Chips Windscreen						Left front	5.	.5	mm
						Right front	6	.5	mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Dry						Right rear	6	.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension	1		
Underbody	Surface Rust - Expected	d for Age & Milea	ge			Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories	-		
Seats	Average					Head lights	~		
Correcto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Radio Knob	s Missing					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		<u> </u>
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
						<u> </u>	1		
Inspected by: Samuel Weir Date: 30 Sep 2024									
I have read and understood this condition guide. Name:									