

Report ID: 26,324,037 Version: 2 24 Oct 2024 Created:

Make:	Volkswagen	Model:	Tiguan	Body Style:	Wagon		Pass	Fail	N/A
Year:	2009	Registration:	LYB40	Reg Expiry:	17 Aug 2025	Engine		-	
	08 Oct 2025	Odometer:	130,566 Kms	Good No:	26324037	Oil level	~		
VIN:	WVGZZZ5NZ9W1008(			Service History		Smoke & fumes	~		
			110000			Performance	~		
	port is not a warranty					Noise	~		
	a guide only. Conside sting undertaken. The					Cooling System	•		
	ical inspection prior to					Coolant condition			
						Performance	<b>v</b>		
Key:	L	-0	SP SP			Radiator / Hoses (visual)	<b>v</b>		
S = scratch	Sec	20	<u>C</u>	10F	*	Transmission	~		
D = dent					HIDS				
R = rust	MIP				SAIR	Operation	~		
PT = paint defe	ect					Noise	~		
C = crack P = pin dent	Ho		ل			Clutch			~
* = decals	sc w db					CV joints	~		
SC = stone chi	ps US			10		Wheel bearings	~		
W = significant scuffs						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	5.	0	mm
						Right front	5.	0	mm
						Left rear	7.	0	mm
Conditions During Body Inspection:						Right rear	7.0		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	II		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	v v		
						Window winder RR	v v		
						Rear view mirrors	v v		
						Radio (basic test only)			
						CD (basic test only)	~		~
						Number of keys	2		~
							2		
Road Con	ditions During Test	: Drive:	Dry			Central locking	~		
Engine Tir	ming Mechanism:	Cambelt				Remote locking	~		
-	of Cam Belt Replac		Io	Kms:		Sat. Nav. (basic test only)			~
Lvidence				11113.		Reversing camera	~		
Inspected by: Kilipati Mae Date: 26 Sep 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....