

Basic Vehicle Condition Guide

Report ID: 26,328,655


Version: 1

Created: 10 Oct 2024

Make: Model: Toyota **Avensis Body Style:** Wagon Year: 2017 Registration: QJS853 Reg Expiry: 09 Jan 2025 WoF Expiry: **Odometer: Good No:** 30 Sep 2025 52,210 Kms 26328655 VIN: 7AT0H63MX23013156 **Next Service:** 62000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

RH side roof rack rail cover missing,

Conditions	Durina	Bodv	Inspection:	Drv

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	Pass V V V V V V V V	Fail	N/A
Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	V V V		
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	V V V		
Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch			
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch			
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch			
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch			
Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch			
Radiator / Hoses (visual) Transmission Operation Noise Clutch	v v		
Transmission Operation Noise Clutch	ν ν		
Operation Noise Clutch	v		
Noise Clutch	'		
Clutch			
	~		
			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	6	.2	mm
Right front	6	.7	mm
Left rear	7	.5	mm
Right rear	7	.1	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			.1
Operation	~		
Electrical / Accessories			.1
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	VVV		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	VVV		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	V		
Number of keys	1	I	1
Central locking	~		
Remote locking	·		
Sat. Nav. (basic test only)			·
Reversing camera	~		

25 Sep 2024

Signature:

Date:

Name: