

Report ID: 26,329,344 Version: 5 05 Nov 2024 Created:

| Make: | Nissan | Model: | Murano | Body Style: | Wagon | | Pass | Fail | N/A |
|--|--------------------------|----------------|------------------------|--------------------|----------------------|------------------------------|---------|---------|----------|
| Year: | 2004 | Registration: | HWY817 | Reg Expiry: | 14 Jul 2025 | Engine | | | <u> </u> |
| WoF Expiry: | 25 Mar 2025 | Odometer: | 192,124 Kms | Good No: | 26329344 | Oil level | ~ | | |
| VIN: | 7AT0DH74X15001480 | Next Service: | 200000 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | ~ | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and t | nis can be arranged fo | r an additional o | harge. | Coolant condition | ~ | | |
| | S R SC | | S SC S SC | | S SC | Performance | ~ | | |
| Key: | SKSC | -0 | s sc s sc | | 530 | Radiator / Hoses (visual) | V | | |
| S = scratch D = dent | | | | | | Transmission | 1 | | L |
| D = dent R = rust S SC S PT C SC | | | | | | Operation | ~ | | |
| PT = paint defect | | | | | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | | | | | | CV joints | ~ | | |
| *= decais | | | | | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs S SC S D SC S D SC S D SC | | | | | | Performance | ~ | | |
| Body Insr | pection Comments | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Bonnet struts weak | | | | | | Tyres (lowest observed tread | d depth | of tyre | es) |
| | | | | | | Left front | 7 | .0 | mm |
| | | | | | | Right front | 6 | .0 | mm |
| | | | | | | Left rear | 6.0 mi | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 6.0 mm | | mm |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| Steering performance | | | | | | | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | • | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | cracked se | ats | | | | Head lights | ~ | | |
| Carranta | Average | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | scratches | scuffs marks | | | | Dashboard warning lights | ~ | | |
| Dachhar | scratches | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | iiu | | | | | Window winder FL | ~ | | |
| | - . | | | |] | Window winder FR | ~ | | |
| General Comments | | | | | Window winder RL | ~ | | | |
| Stereo display not showing. Remote nw. Requires engine mount | | | | | | Window winder RR | ~ | | |
| | - | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | | ~ | |
| | | | | | | CD (basic test only) | | ~ | |
| | | | | | | Number of keys | 2 | 1 | |
| Road Con | Central locking | ~ | | | | | | | |
| E Frankis - 74 | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Inspected by: Gary Adams Date: 26 Sep 2024 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: