

Basic Vehicle Condition Guide

Report ID: 26,330,333


Version: 4

Created: 01 Oct 2024

Make: Model: CRV Honda **Body Style:** Wagon Year: 2006 Registration: JML553 Reg Expiry: 24 Feb 2025 WoF Expiry: **Odometer: Good No:** 24 Sep 2025 173,121 Kms 26330333 VIN: 7AT08G7HX16004099 Next Service: 183100 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips in windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Vehicle drove well

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jayden Roxburgh Date: 01 Oct 2024

Name:

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual)	Oil level			
Smoke & fumes Performance Noise Cooling System Coolant condition Performance				
Cooling System Coolant condition Performance				
Cooling System Coolant condition Performance	Smoke & fumes	~		
Cooling System Coolant condition Performance	Performance	~		
Coolant condition Performance	Noise	~		
Performance 🗸	Cooling System			
	Coolant condition	~		
Radiator / Hoses (visual)	Performance	~		
	Radiator / Hoses (visual)	~		
Transmission	Transmission	•		
Operation 🗸	Operation	~		
Operation Noise V	Noise	~		
Clutch	Clutch			~
CV joints 🗸	CV joints	~		
Wheel bearings 🗸	Wheel bearings	~		
Brakes	Brakes	•		
Performance 🗸	Performance	~		
Hand Brake	Hand Brake	~		
Tyres (lowest observed tread depth of tyres)	Tyres (lowest observed tread	d depth	of tyre	2s)
Left front 8 mm	Left front	8		mm
Right front 8 mm	Right front	8		mm
Left rear 8 mm	Left rear	8		mm
Right rear 8 mm	Right rear	8		mm
Spare Yes	Spare		Yes	
Suspension	Suspension			
Suspension performance 🗸	Suspension performance	~		
Suspension performance Steering performance Shock absorbers	Steering performance	~		
Shock absorbers 🗸	Shock absorbers	~		
Air Conditioning / Heater				
Operation 🗸	Operation	~		
Electrical / Accessories				
Head lights 🗸	Head lights	~		
Tail lights 🗸	Tail lights	~		
Indicators 🗸	Indicators	~		
Dashboard warning lights 🗸	Dashboard warning lights	~		
Wipers (front & rear)	•	~		
Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors		~		
Window winder FR 🗸		~		
Window winder RL	Window winder RL	~		
Window winder RR 🗸	Window winder RR	~		
Rear view mirrors	Rear view mirrors	~		
Radio (basic test only)	Radio (basic test only)			
CD (basic test only)	·	~		
Number of keys 1	Number of keys	1	1	
Central locking	Central locking	~		
Remote locking 🗸	Remote locking	~		
Sat. Nav. (basic test only)	Sat. Nav. (basic test only)			~
Reversing camera 🗸	Reversing camera	'		

Signature: