

Basic Vehicle Condition Guide

Report ID: 26,332,569


Version: 2

Created: 04 Oct 2024

Make: Model: Chevrolet MW**Body Style:** Hatchback Year: 2007 Registration: NGC93 Reg Expiry: 05 Oct 2024 WoF Expiry: **Odometer:** 09 Jul 2025 96,428 Kms **Good No:** 26332569 VIN: 7AT02R4WX20352126 Next Service: 100,000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	marks		
Carpets	Average		
Panels	scratches scuffs marks		
Dashboard	scratches		

General Comments

Key is taped up - no internals for central locking

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Gary Adams Date: 01 Oct 2024

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V V V V V V V V V V V V V V V V V			
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes	V V V V V V V V V V V V V V V V V V V			
Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes	V V V V V V V			
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes	V V V V V V			
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes	V V V V V			
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes	V V V V V			
Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes	V V V			
Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes	V V V			
Transmission Operation Noise Clutch CV joints Wheel bearings Brakes	V V			
Operation Noise Clutch CV joints Wheel bearings Brakes	V V			
Noise Clutch CV joints Wheel bearings Brakes	V V			
Clutch CV joints Wheel bearings Brakes	V			
CV joints Wheel bearings Brakes				
Wheel bearings Brakes			~	
Brakes	<i> </i>			
	~			
Performance	l			
	~			
Hand Brake	~			
Tyres (lowest observed tread	l depth	of tyre	 es)	
Left front	5	.0	mm	
Right front	5	.0	mm	
Left rear	6	.0	mm	
Right rear	6	.0	mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	\(\triangle \)			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	\(\times \) \(\t			
Window winder FL	~			
Window winder FR	~			
Window winder RL	<i>v</i>			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	<i>v</i>			
CD (basic test only)	~			
Number of keys	1			
	·			
<u>*</u>			./	
Central locking			-	
Central locking Remote locking				
Central locking			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	

I have read and understood this condition guide.

Name:

Signature: