

Basic Vehicle Condition Guide

Report ID: 26,333,298


Version: 1

Created: 27 Sep 2024

Make: Model: Z3 **BMW Body Style:** Sports Car Year: 2002 Registration: CSS582 Reg Expiry: 05 Nov 2024 WoF Expiry: **Odometer:** 10 Oct 2024 207,586 Kms **Good No:** 26333298 VIN: WBACN12010LL73433 Next Service: Unknown **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Paint defect on both mirrors. Rear window ripped from soft top.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak. Transmission leak.

| Interior | Comments |
|----------|----------|
| | |

| Seats | Poor, Driver's height adjuster fail |
|-----------|-------------------------------------|
| Carpets | Good |
| Panels | Average |
| Dashboard | Good |

General Comments

No antifreeze in coolant. Smoke from exhaust.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Caleb Spicer Lee Date: 27 Sep 2024

Name:

| | Pass | Fail | N/A | | |
|------------------------------|-----------------------------------------|---------|----------|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | | ~ | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | | ~ | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | | | ~ | | |
| Wheel bearings | ~ | | | | |
| Brakes | • | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | |
| Left front | | 5 | mm | | |
| Right front | 6 | | mm | | |
| Left rear | 3.5 | | mm | | |
| Right rear | 3 | .5 | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | VVV | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | | | ~ | | |
| Window winder RR | | | ~ | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 1 | ı | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | ' | | |
| | | | | | |

Signature: