

## **Basic Vehicle Condition Guide**

Report ID: 26,335,131


Version: 1

Created: 07 Oct 2024

Make: Model: **Body Style:** Holden Colorado Utility Year: 2019 Registration: MLB659 Reg Expiry: 25 Mar 2025 WoF Expiry: **Odometer: Good No:** 26 Sep 2025 65,349 Kms 26335131 VIN: MMU148LK0LH61402 Next Service: 74,000 kms Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Rwd

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

## **General Comments**

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Vasanthakumar Mayilswamy Inspected by:

Created	u: 0	Oct 2	024		
	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	~				
Performance	/				
Noise	~				
Cooling System			•		
Coolant condition	~				
Performance	<b>V</b>				
Radiator / Hoses (visual)	~				
Transmission			•		
Operation	~				
Noise	>				
Clutch			~		
CV joints	~				
Wheel bearings	/				
Brakes			•		
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread depth of tyres)					
Left front	7	7	mm		
Right front	7	7	mm		
Left rear	4	1	mm		
Right rear	4	1	mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	<b>&gt;</b>				
Shock absorbers	>				
Air Conditioning / Heater					
Operation	~				
Electrical / Accessories					
Head lights	~				
Tail lights	~				
Indicators	~				
Dashboard warning lights	V V V V V V				
Wipers (front & rear)	~				
Window winder FL	~				
Window winder FR	~				
Window winder RL	~				
Window winder RR	~				
Rear view mirrors	~				
Radio (basic test only)	~				
CD (basic test only)			~		
Number of keys 2					
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)	~				
Reversing camera	~				
D					

Date: 07 Oct 2024

have read and understood this condition guide.	Name:	Signature: