

Report ID: 26,335,827 Version: 1 15 Oct 2024 Created:

Make:	Daihatsu	Model:	Sirion	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	<b>Registration:</b>	EPN589	<b>Reg Expiry:</b>	30 Oct 2024	Engine			
WoF Expiry:	16 Aug 2025	Odometer:	73,956 Kms	Good No:	26335827	Oil level	~		
VIN:	JDAM301S001073551	Next Service:	83000	Service Histor	<b>y:</b> No	Smoke & fumes	V		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	S SC S					Performance	~		
Key:	SSC S	-0	S D SC SC	SC	sc	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	S PT SC			715	SDPT	Operation	~		
PT = paint defe		F		$\left( \left  \right\rangle \right)$		Noise	~		
C = crack					S PT SC	Clutch	~		
P = pin dent	HIC				세비	CV joints	~		
* = decals	S PT SC 916			-Jul-	ELD SPT	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S S SC S D SC S D SC S D SC						Performance	~		
Dealer		Note: son	ne defects & blemishes	may not be disc	layed in the diagram	Hand Brake	~		+
body inspection comments						Tyres (lowest observed tread	•	oftvre	es)
Both mirror casings need paint,						Left front 6.3 mm			
						Right front		.5 .6	mm
						Left rear	-	.0 .6	mm
Conditions During Pody Increation Druce						Right rear			 mm
Conditions During Body Inspection: Dry						Spare	6.6 mm Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
		<b>-</b>				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	v		
Interior Comments						Operation V Electrical / Accessories			
Seats Good									
Seals							~		
Carpets	Good					Tail lights Indicators	<b>v</b>		
	Good						<b>v</b>		
Panels						Dashboard warning lights	<b>v</b>		
Dashboa	rd Good					Wipers (front & rear) Window winder FL	~		
						Window winder FL Window winder FR	<b>v</b>		+
General (	Comments					Window winder FR Window winder RL	V		
Drives okay							~		
Freshly serv						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine Tir	ming Mechanism:	Timing				Remote locking	~		<u> </u>
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Lvidence				NITIS.		Reversing camera			~
Inspected by: Donovan Matara Date: 01 Oct 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....