

## **Basic Vehicle Condition Guide**

Report ID: 26,336,301


Version: 3

Created: 08 Oct 2024

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2020 Registration: NDE466 Reg Expiry: 20 Apr 2025 **Odometer:** WoF Expiry: 21 Oct 2024 237,313 Kms **Good No:** 26336301 VIN: MR0BA3CD00012277( Next Service: 247,200 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Hard lid misaligned, not latching Paint worn in drivers door sill Large stone chips in windscreen Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

## **General Comments**

Right interior vent damaged

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Samuel Weir Date: 08 Oct 2024

Name: .....

Cooling System	/ / / / epth	of tyre	V
Smoke & fumes Performance Noise  Cooling System Coolant condition Performance Radiator / Hoses (visual)  Transmission Operation Noise Clutch CV joints Wheel bearings  Brakes Performance Hand Brake Tyres (lowest observed tread delayed)	/ / / / epth	of tyre	V
Cooling System  Coolant condition Performance Radiator / Hoses (visual)  Transmission Operation Noise Clutch CV joints Wheel bearings  Brakes Performance Hand Brake  Tyres (lowest observed tread delayed)	/ / / / epth	of tyre	V
Cooling System  Coolant condition Performance Radiator / Hoses (visual)  Transmission Operation Noise Clutch CV joints Wheel bearings  Brakes Performance Hand Brake Tyres (lowest observed tread delayed) Left front	/ / / / epth	of tyre	V
Cooling System  Coolant condition Performance Radiator / Hoses (visual)  Transmission Operation Noise Clutch CV joints Wheel bearings  Brakes Performance Hand Brake Tyres (lowest observed tread delayed) Left front	/ / / / epth	of tyre	V
Coolant condition Performance Radiator / Hoses (visual)  Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread delayed) Left front	/ / / epth	of tyre	V
Performance Radiator / Hoses (visual)  Transmission Operation Noise Clutch CV joints Wheel bearings  Brakes Performance Hand Brake Tyres (lowest observed tread delayed) Left front	/ / / epth	of tyre	V
Transmission  Operation  Noise  Clutch  CV joints  Wheel bearings  Brakes  Performance  Hand Brake  Tyres (lowest observed tread delayed)  Left front	/ / / epth	of tyre	V
Transmission  Operation  Noise  Clutch  CV joints  Wheel bearings  Brakes  Performance  Hand Brake  Tyres (lowest observed tread delayed)  Left front	/ / / epth	of tyre	V
Transmission  Operation  Noise  Clutch  CV joints  Wheel bearings  Brakes  Performance  Hand Brake  Tyres (lowest observed tread delayed)  Left front	/ / / epth	of tyre	<b>V</b>
Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake Tyres (lowest observed tread delayed) Left front		of tyre	V
Clutch CV joints Wheel bearings  Brakes Performance Hand Brake  Tyres (lowest observed tread delayed) Left front		of tyre	V
CV joints  Wheel bearings  Brakes  Performance Hand Brake  Tyres (lowest observed tread delayed) Left front		of tyre	<b>V</b>
Wheel bearings  Brakes  Performance Hand Brake  Tyres (lowest observed tread delayed) Left front		of tyre	(c)
Wheel bearings  Brakes  Performance Hand Brake  Tyres (lowest observed tread delayed) Left front		of tyre	
Performance Hand Brake  Tyres (lowest observed tread delete front		of tyre	.c)
Hand Brake  Tyres (lowest observed tread de Left front		of tyre	se)
Tyres (lowest observed tread do		of tyre	) .
Left front		of tyre	ر د) احا
Left front			31
Right front		0	mm
	6.0		mm
Left rear		.0	mm
Right rear	6.		mm
Spare	- 0.	Yes	
Suspension		103	
Suspension performance	_		
Steering performance			
Shock absorbers			
Air Conditioning / Heater			
Operation			
Electrical / Accessories			
Head lights	_		
Tail lights			
Indicators			
Dashboard warning lights	_		
Wipers (front & rear)	/		
Window winder FL			
Window winder FL	_		
Window winder RL	/		
Radio (basic test only)	_		
CD (basic test only)			~
Number of keys 2			
Central locking	_		
Remote locking	/		
Sat. Nav. (basic test only)	/		
Reversing camera	_		

Signature: .....