

Report ID: 26,338,886 Version: 1 01 Oct 2024 Created:

Make:	Mini	Model:	Cooper S	Body Style:	SUV		Pass	Fail	N/A	
Year:	2013	Registration:	LNQ897	Reg Expiry:	30 Nov 2024	Engine	•			
WoF Expiry:	18 Sep 2025	Odometer:	164,535 Kms	Good No:	26338886	Oil level	~			
VIN:	WMWZC52020WP818	Next Service:	175000km	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	r an additional c	harge.	Coolant condition	~			
	W		DP D		S	Performance	~			
Key:		-0	DP D			Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent R = rust	sc			715	HILS	Operation	~			
PT = paint defe				$\left[\right] \left[\right]$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HID				74114	CV joints	~			
* = decals	s sc 916			-NG		Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs W S W S						Performance	~			
Dealerteen	<u></u>	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body inspection Comments						Tyres (lowest observed tread depth of tyres)			es)	
Stone chips in windscreen									mm	
						Right front		7	mm	
						Left rear		1	mm	
Conditions During Body Inspection:						Right rear			 mm	
Conditions During Body Inspection: Dry						Right rear 5 mm Spare No				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	-	•				Suspension performance	~			
						Steering performance	• •			
						Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation				
Interior Comments						Electrical / Accessories				
Seats Good						Head lights				
Seals						Tail lights	~			
Carpets	Good						~			
	Good					Dashboard warning lights				
Panels						Wipers (front & rear)	V			
Dashboa	rd Good					Window winder FL	~			
						Window winder FL Window winder FR	V			
General (Comments						V			
Vehicle drove well						Window winder RL	V			
						Window winder RR	V			
						Rear view mirrors	V			
						Radio (basic test only)	~			
						CD (basic test only)	v			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
Engine Tir	ming Mechanism:	Timing	Chain			Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
						Reversing camera			~	
Inspected by: Aaron Johnson Date: 01 Oct 2024										

I have read and understood this condition guide.

Name:

Signature: