

Basic Vehicle Condition Guide

Report ID: 26,340,629


Version: 3

Created: 08 Oct 2024

Make: Model: Holden Colorado **Body Style:** Utility Year: 2016 Registration: JNN320 Reg Expiry: 14 Mar 2025 WoF Expiry: **Odometer: Good No:** 08 Feb 2025 83,924 Kms 26340629 VIN: MMU148EK0GH62909 Next Service: 95272 kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Shift knob and boot worn. Rear bumper RHS pushed in. Tailgate doesn't latch properly. Missing roof antenna.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

RWD

Interior Comments			
Seats	Poor		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Aftermarket roof light with dash switch. W/S stone chip out of CVA. Driver seat tear and adjustment lever broken.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Eleoit Kumar

	Pass	Fail	N/A
Engine		l	
Oil level	~		
Smoke & fumes	~		
Performance	V		
Noise	~		
Cooling System			
Coolant condition	V		
Performance	•		
Radiator / Hoses (visual)	-/		
Transmission	•		
Operation	,		
Noise	V		
Clutch	-		
CV joints	_		~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	l depth	of tyre	es)
Left front	8	.0	mm
Right front	8	.0	mm
Left rear	7.0		mm
Right rear	6.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights			
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	VVVVV		
Window winder RL	~		
Window winder RR	<i>v</i>		
Rear view mirrors	V		
Radio (basic test only)	-	.,	
<u> </u>		-	.,
CD (basic test only)			<i>'</i>
Number of keys	1		
Central locking	~		
Remote locking	~		
	İ	ĺ	V
Sat. Nav. (basic test only) Reversing camera			

I have read and understood this condition guide.

Name:

Signature: