

Basic Vehicle Condition Guide

Report ID: 26,346,264


Version: 2

14 Nov 2024 Created:

Make: LDV Model: G10 **Body Style:** Van Year: 2023 Registration: PWG901 Reg Expiry: 29 Apr 2025 WoF Expiry: **Odometer: Good No:** 30 Apr 2026 12,318 Kms 26346264 VIN: LSKG4GL1XNA109089 Next Service: 20,000 km Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

RWD.

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

| | _ |
|---------|----------|
| General | Comments |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

14 Nov 2024 Inspected by: Marlon Espena Date:

Name:

| | Pass | Fail | N/A | | |
|--|--------------|------|----------|--|--|
| Engine | | - | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | \(\times \) | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | • | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | |
| Left front | , | 8 | mm | | |
| Right front | 8 | | mm | | |
| Left rear | 8 | | mm | | |
| Right rear | 8 | | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | \(\times \) | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | \(\times \) | | | | |
| Wipers (front & rear) | | | | | |
| Window winder FL | / | | | | |
| Window winder FR | - | | | | |
| Window winder RL | | | ~ | | |
| Window winder RR | | | ~ | | |
| Rear view mirrors | • | | | | |
| Radio (basic test only) | ~ | | <u> </u> | | |
| CD (basic test only) | | | ' | | |
| Number of keys | 1 | | | | |
| Central locking | <i>'</i> | | | | |
| Remote locking | - | | _ | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | | | |

Signature: