

Basic Vehicle Condition Guide

Report ID: 26,349,750

Version: 1


Created: 16 Oct 2024

Make: Model: Mazda Axela **Body Style:** Hatchback Year: 2012 Registration: NQW763 Reg Expiry: 22 Oct 2024 **Odometer:** WoF Expiry: 23 Oct 2025 121,002 Kms **Good No:** 26349750

VIN: 7AT0C13JX21200234 Next Service: Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection	:
-----------------------------------	---

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Burble Tune

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Safecar Date: 07 Oct 2024

Name:

Pass	Fail	N/A			
		1			
~					
~					
~					
~					
~					
~					
'					
~					
~					
v					
~					
~					
Brakes					
~					
~					
Tyres (lowest observed tread depth of tyres)					
5		mm			
5		mm			
5		mm			
5		mm			
Yes					
~					
~					
~					
Air Conditioning / Heater					
Operation 🗸					
Electrical / Accessories					
~					
~					
~					
>					
'					
~					
~					
~					
~					
~					
V					
-					
V					
\(\triangle \)					
\(\triangle \)					
\(\triangle \)					
	ン	マ			

Signature: