

Report ID: 26,359,658 Version: 2 15 Nov 2024 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2018	Registration:	LNW622	Reg Expiry:	13 Aug 2024	Engine			
WoF Expiry:	31 Oct 2025	Odometer:	148,392 Kms	Good No:	26359658	Oil level	~		
VIN:	MMU148LK0KH60049	Next Service:	159,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechar	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance			~
Key:	SC	-0	P D	-161-	S W	Radiator / Hoses (visual)	~		-
S = scratch						Transmission			
D = dent	SC 6/6			The		Operation	~		
R = rust PT = paint def	ect NP			\prod		Noise	~		
C = crack					SC	Clutch	~		
P = pin dent	110				세비	CV joints	~		
* = decals	DSC 916			The	EL SPW	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs SC S		P SC D R P		SC	Performance	~		
		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
l , ,	pection Comments			, ,	, ,	Tyres (lowest observed tread	-	of tvre	l s)
Stone chip in windscreen C.V.A						Left front 8.0 mm			
						Right front	8.		mm
						Left rear	5.		mm
Condition	as During Pady Inc	action	Deri			Right rear			mm
Conditions During Body Inspection: Dry						Right rear 5.0 mn Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Rear wheel	-	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	Ird Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Seats stained						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking	~		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		
L									1
Inspected by: Andre Richardson Date: 16 Oct 2024									

I have read and understood this condition guide.

Name:

Signature: